

Tune-up Procedure

The transmitter is tested during unit production by measuring the output strength of a 2.457 GHz continuous wave with a nearby receiver. The output signal strength is optimized and a pass/fail threshold is determined by engineering during product development.