



Internal Photographs of Transmitter Board



Metal covering is integral part of Transceiver IC chip



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: O5AHGT01  
Test #: 150324  
Test to: CFR47 (15C), RSS-210  
File: O5AHGT01IntPho

SN: FBF-8  
FCC ID#: IPH-02567  
IC: 1792A-02567  
Date: May 10, 2015  
Page 1 of 1