


Main PCB top side



Transmitter sections

PCB bottom side





Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A02759  
Test #: 151015  
Test to: CFR47 15C, RSS-247  
File: A02759 IntPho

SN: EE6  
FCC ID: IPH-02759  
IC: 1792A-02759  
Date: February 3, 2016



## Antenna placements



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1


Garmin International, Inc.  
Model: A02759  
Test #: 151015  
Test to: CFR47 15C, RSS-247  
File: A02759 IntPho

SN: EE6  
FCC ID: IPH-02759  
IC: 1792A-02759  
Date: February 3, 2016

Antenna PCB top



Antenna PCB side



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A02759  
Test #: 151015  
Test to: CFR47 15C, RSS-247  
File: A02759 IntPho

SN: EE6  
FCC ID: IPH-02759  
IC: 1792A-02759  
Date: February 3, 2016