

There is no transmitter tuning available to customers for the GMN-01589. The units are tested in the factory on a pass/fail criterion.