


Top Side Transmitter Board



Bottom Side Transmitter Board




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1


Garmin International, Inc.
Model: A03139
Test #: 161005
Test to: CFR47 15C, RSS-210, RSS-247
File: A03139 IntPho

SN's: ENG1, 6, ENG1, 25
FCC ID: IPH-03139
IC: 1792A-03139
Date: November 17, 2016
Page 1 of 4

Transmitter Board with Antenna location



Top Side Transmitter Board Shields



Bottom Side Transmitter Board Shields


Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03139
Test #: 161005
Test to: CFR47 15C, RSS-210, RSS-247
File: A03139 IntPho

SN's: ENG1, 6, ENG1, 25
FCC ID: IPH-03139
IC: 1792A-03139
Date: November 17, 2016
Page 2 of 4



Top Side Transmitter Board no shields




Bottom Side Transmitter Board no shields

Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03139
Test #: 161005
Test to: CFR47 15C, RSS-210, RSS-247
File: A03139 IntPho

SN's: ENG1, 6, ENG1, 25
FCC ID: IPH-03139
IC: 1792A-03139
Date: November 17, 2016
Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03139
Test #: 161005
Test to: CFR47 15C, RSS-210, RSS-247
File: A03139 IntPho

SN's: ENG1, 6, ENG1, 25
FCC ID: IPH-03139
IC: 1792A-03139
Date: November 17, 2016
Page 4 of 4