



Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03272
Test #: 170828 1206
Test to: CFR47 15C, RSS-247, RSS-210
File: A03272 TSup

SN's: 3959315045 / 5054
FCC ID: IPH-03272
IC: 1792A-03272
Date: January 12, 2018
Page 1 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03272
Test #: 170828 1206
Test to: CFR47 15C, RSS-247, RSS-210
File: A03272 TSup

SN's: 3959315045 / 5054
FCC ID: IPH-03272
IC: 1792A-03272
Date: January 12, 2018
Page 2 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03272
Test #: 170828 1206
Test to: CFR47 15C, RSS-247, RSS-210
File: A03272 TSup

SN's: 3959315045 / 5054
FCC ID: IPH-03272
IC: 1792A-03272
Date: January 12, 2018
Page 3 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03272
Test #: 170828 1206
Test to: CFR47 15C, RSS-247, RSS-210
File: A03272 TSup

SN's: 3959315045 / 5054
FCC ID: IPH-03272
IC: 1792A-03272
Date: January 12, 2018
Page 4 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03272
Test #: 170828 1206
Test to: CFR47 15C, RSS-247, RSS-210
File: A03272 TSup

SN's: 3959315045 / 5054
FCC ID: IPH-03272
IC: 1792A-03272
Date: January 12, 2018
Page 5 of 5