


Main PCB no shield




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03298  
Test #: 180212  
Test to: CFR47 15C, RSS-247, RSS-210  
File: A03298 Short Term Conf IntPho

SN: 3964600133 / 123  
FCC ID: IPH-03298  
IC: 1792A-03298  
Date: July 4, 2018  
Page 1 of 5

Main PCB with shield




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03298  
Test #: 180212  
Test to: CFR47 15C, RSS-247, RSS-210  
File: A03298 Short Term Conf IntPho

SN: 3964600133 / 123  
FCC ID: IPH-03298  
IC: 1792A-03298  
Date: July 4, 2018  
Page 2 of 5

Main PCB back shields removed




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03298  
Test #: 180212  
Test to: CFR47 15C, RSS-247, RSS-210  
File: A03298 Short Term Conf IntPho

SN: 3964600133 / 123  
FCC ID: IPH-03298  
IC: 1792A-03298  
Date: July 4, 2018  
Page 3 of 5

Main PCB back shields on




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1


Garmin International, Inc.  
Model: A03298  
Test #: 180212  
Test to: CFR47 15C, RSS-247, RSS-210  
File: A03298 Short Term Conf IntPho

SN: 3964600133 / 123  
FCC ID: IPH-03298  
IC: 1792A-03298  
Date: July 4, 2018  
Page 4 of 5

USB and Torch FPC front



USB and Torch FPC back



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03298  
Test #: 180212  
Test to: CFR47 15C, RSS-247, RSS-210  
File: A03298 Short Term Conf IntPho

SN: 3964600133 / 123  
FCC ID: IPH-03298  
IC: 1792A-03298  
Date: July 4, 2018  
Page 5 of 5