



## Test setup photographs




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: GMN-01912  
Test: 190506  
Test to: 47 CFR 15C, RSS-210, RSS-247  
File: GMN01912 Short Term Conf TSup

SN's: 5MZ200112, 5MZ200082  
FCC ID: IPH-03333  
IC: 1792A-03333  
Date: October 2, 2019  
Page 1 of 4





Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: GMN-01912  
Test: 190506  
Test to: 47 CFR 15C, RSS-210, RSS-247  
File: GMN01912 Short Term Conf TSup

SN's: 5MZ200112, 5MZ200082  
FCC ID: IPH-03333  
IC: 1792A-03333  
Date: October 2, 2019  
Page 2 of 4







Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: GMN-01912  
Test: 190506  
Test to: 47 CFR 15C, RSS-210, RSS-247  
File: GMN01912 Short Term Conf TSup

SN's: 5MZ200112, 5MZ200082  
FCC ID: IPH-03333  
IC: 1792A-03333  
Date: October 2, 2019  
Page 3 of 4





Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: GMN-01912  
Test: 190506  
Test to: 47 CFR 15C, RSS-210, RSS-247  
File: GMN01912 Short Term Conf TSup

SN's: 5MZ200112, 5MZ200082  
FCC ID: IPH-03333  
IC: 1792A-03333  
Date: October 2, 2019  
Page 4 of 4