



Test setup photographs



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.    SN's: 5FK000182 / 5FK000158  
Model: A03363  
Test #: 180604  
Test to: CFR47 15C, RSS-Gen RSS-210  
File: A03363 Short Term Conf TSup

FCC ID: IPH-03363  
IC: 1792A-03363  
Date: August 31, 2018  
Page 1 of 3





Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc. SN's: 5FK000182 / 5FK000158  
Model: A03363  
Test #: 180604  
Test to: CFR47 15C, RSS-Gen RSS-210  
File: A03363 Short Term Conf TSup

FCC ID: IPH-03363  
IC: 1792A-03363  
Date: August 31, 2018  
Page 2 of 3





Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc. SN's: 5FK000182 / 5FK000158  
Model: A03363  
Test #: 180604  
Test to: CFR47 15C, RSS-Gen RSS-210  
File: A03363 Short Term Conf TSup

FCC ID: IPH-03363  
IC: 1792A-03363  
Date: August 31, 2018  
Page 3 of 3