


Main PCB no shield




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03402
Test #: 180108
Test to: CFR47 15C, RSS-Gen, RSS-210
File: A03402 Short Term Conf IntPho

SN: 3963727968 / 27915
FCC ID: IPH-03402
IC: 1792A-03402
Date: March 1, 2018
Page 1 of 5

Main PCB side A with shield cover removed and Micro USB PCB




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03402
Test #: 180108
Test to: CFR47 15C, RSS-Gen, RSS-210
File: A03402 Short Term Conf IntPho

SN: 3963727968 / 27915
FCC ID: IPH-03402
IC: 1792A-03402
Date: March 1, 2018
Page 2 of 5

Main PCB side A and Antennas




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03402
Test #: 180108
Test to: CFR47 15C, RSS-Gen, RSS-210
File: A03402 Short Term Conf IntPho

SN: 3963727968 / 27915
FCC ID: IPH-03402
IC: 1792A-03402
Date: March 1, 2018
Page 3 of 5

Main PCB side B and Micro USB PCB



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03402
Test #: 180108
Test to: CFR47 15C, RSS-Gen, RSS-210
File: A03402 Short Term Conf IntPho

SN: 3963727968 / 27915
FCC ID: IPH-03402
IC: 1792A-03402
Date: March 1, 2018
Page 4 of 5

Main PCB removed showing battery



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03402
Test #: 180108
Test to: CFR47 15C, RSS-Gen, RSS-210
File: A03402 Short Term Conf IntPho

SN: 3963727968 / 27915
FCC ID: IPH-03402
IC: 1792A-03402
Date: March 1, 2018
Page 5 of 5