



Test setup photographs



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03485  
Test #: 181015  
Test to: CFR47 15, RSS-210, RSS-247  
File: A03485 Short Term Conf TSUp


SN's: 88501 / 88605  
FCC ID: IPH-03485  
IC: 1792A-03485  
Date: February 20, 2019  
Page 1 of 4



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03485  
Test #: 181015  
Test to: CFR47 15, RSS-210, RSS-247  
File: A03485 Short Term Conf TSup

SN's: 88501 / 88605  
FCC ID: IPH-03485  
IC: 1792A-03485  
Date: February 20, 2019  
Page 2 of 4



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03485  
Test #: 181015  
Test to: CFR47 15, RSS-210, RSS-247  
File: A03485 Short Term Conf TSup

SN's: 88501 / 88605  
FCC ID: IPH-03485  
IC: 1792A-03485  
Date: February 20, 2019  
Page 3 of 4



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03485  
Test #: 181015  
Test to: CFR47 15, RSS-210, RSS-247  
File: A03485 Short Term Conf TSup

SN's: 88501 / 88605  
FCC ID: IPH-03485  
IC: 1792A-03485  
Date: February 20, 2019  
Page 4 of 4