



Test setup photographs



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03562
Test #: 180904
Test to: CFR47 15.249, RSS-210, RSS-Gen
File: A03562 Short Term Conf TSup


SN's: 984512717 / 39733 09969
FCC ID: IPH-03562
IC: 1792A-03562
Date: October 25, 2018
Page 1 of 3



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03562
Test #: 180904
Test to: CFR47 15.249, RSS-210, RSS-Gen
File: A03562 Short Term Conf TSup

SN's: 984512717 / 39733 09969
FCC ID: IPH-03562
IC: 1792A-03562
Date: October 25, 2018
Page 2 of 3



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03562
Test #: 180904
Test to: CFR47 15.249, RSS-210, RSS-Gen
File: A03562 Short Term Conf TSup

SN's: 984512717 / 39733 09969
FCC ID: IPH-03562
IC: 1792A-03562
Date: October 25, 2018
Page 3 of 3