




Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03672
Test: 190218
Test to: 47 CFR 15C, RSS-210 RSS-247
File: A03672 TSup


SN's: 3989371048 / 3989371063
FCC ID: IPH-03672
IC: 1792A-03672
Date: April 19, 2019
Page 1 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03672
Test: 190218
Test to: 47 CFR 15C, RSS-210 RSS-247
File: A03672 TSup


SN's: 3989371048 / 3989371063
FCC ID: IPH-03672
IC: 1792A-03672
Date: April 19, 2019
Page 2 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03672
Test: 190218
Test to: 47 CFR 15C, RSS-210 RSS-247
File: A03672 TSup

SN's: 3989371048 / 3989371063
FCC ID: IPH-03672
IC: 1792A-03672
Date: April 19, 2019
Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03672
Test: 190218
Test to: 47 CFR 15C, RSS-210 RSS-247
File: A03672 TSup

SN's: 3989371048 / 3989371063
FCC ID: IPH-03672
IC: 1792A-03672
Date: April 19, 2019
Page 4 of 4