



Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-02303
Test: 191028
Test to: CFR47 15C, RSS-210, RSS-247
File: GMN02303 TSup


SN's: FF3, F17
FCC ID: IPH-03880
IC: 1792A-03880
Date: April 9, 2020
Page 1 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-02303
Test: 191028
Test to: CFR47 15C, RSS-210, RSS-247
File: GMN02303 TSup


SN's: FF3, F17
FCC ID: IPH-03880
IC: 1792A-03880
Date: April 9, 2020
Page 2 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-02303
Test: 191028
Test to: CFR47 15C, RSS-210, RSS-247
File: GMN02303 TSup


SN's: FF3, F17
FCC ID: IPH-03880
IC: 1792A-03880
Date: April 9, 2020
Page 3 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-02303
Test: 191028
Test to: CFR47 15C, RSS-210, RSS-247
File: GMN02303 TSup

SN's: FF3, F17
FCC ID: IPH-03880
IC: 1792A-03880
Date: April 9, 2020
Page 4 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-02303
Test: 191028
Test to: CFR47 15C, RSS-210, RSS-247
File: GMN02303 TSup

SN's: FF3, F17
FCC ID: IPH-03880
IC: 1792A-03880
Date: April 9, 2020
Page 5 of 5