

4740 Discovery Drive | Lincoln, NE 68521 tel- 402.323.6233 | tel -888.657.6860 | fax - 402.323.6238 info@nceelabs.com | http://nceelabs.com

Date: 2021 June 15

Subject: Request for Class II permissive change

FCC ID: IPH-04041

Per Part 2.1043 and 'KDB 178919 D01 v06, we would like to request a Class II permissive change on the above referenced grant of certification. Part of the RF transceiver which is an integrated circuit on-chip has been changed. The new chip has the same basic function as the old chip, from an external perspective.

The transmitter has been re-tested in full to ensure that there were no changes to the radio parameters. The additional Part 15 radios on the devices have not been changed. Testing was performed to ensure there was no degradation in the performance of these transmitters as well.

Updated test reports, schematics, internal photos and test setup photos have been provided to document the change. All other documentation from the original grant remains unchanged.

Thank you,

Nic Johnson Technical Manager NCEE Labs 402-323-6233 njohnson@nceelabs.com