

Appendix D. SAR Test Setup Photos

Head Exposure Condition



Front at 10 mm

Body-Worn Exposure Condition



Front at 5 mm



Back at 5 mm


Extremity Exposure Condition



Back at 0 mm



Left Side at 0 mm



Right Side at 0 mm



Top Side at 0 mm



Bottom Side at 0 mm