

Internal photographs of equipment under test
Inside (Planar Inverted F Antenna (PIFA) locations)




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A04455
Test: 220124
Test to: CFR47 15C, RSS-210, RSS-247
File: A04455 Short Term Conf IntPho r1

SN's: 39F004859 / 3401543685
FCC ID: IPH-04455
IC: 1792A-04455
Date: April 28, 2022
Page 1 of 9

Top with Shield




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A04455
Test: 220124
Test to: CFR47 15C, RSS-210, RSS-247
File: A04455 Short Term Conf IntPho r1

SN's: 39F004859 / 3401543685
FCC ID: IPH-04455
IC: 1792A-04455
Date: April 28, 2022
Page 2 of 9

Top Shield removed



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A04455
Test: 220124
Test to: CFR47 15C, RSS-210, RSS-247
File: A04455 Short Term Conf IntPho r1

SN's: 39F004859 / 3401543685
FCC ID: IPH-04455
IC: 1792A-04455
Date: April 28, 2022
Page 3 of 9

Bottom With Shield




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A04455
Test: 220124
Test to: CFR47 15C, RSS-210, RSS-247
File: A04455 Short Term Conf IntPho r1

SN's: 39F004859 / 3401543685
FCC ID: IPH-04455
IC: 1792A-04455
Date: April 28, 2022
Page 4 of 9

Bottom Shield removed and Antenna Connection point




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A04455
Test: 220124
Test to: CFR47 15C, RSS-210, RSS-247
File: A04455 Short Term Conf IntPho r1

SN's: 39F004859 / 3401543685
FCC ID: IPH-04455
IC: 1792A-04455
Date: April 28, 2022
Page 5 of 9

Antenna Locations




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A04455
Test: 220124
Test to: CFR47 15C, RSS-210, RSS-247
File: A04455 Short Term Conf IntPho r1

SN's: 39F004859 / 3401543685
FCC ID: IPH-04455
IC: 1792A-04455
Date: April 28, 2022
Page 6 of 9

Bottom Support PCB



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A04455
Test: 220124
Test to: CFR47 15C, RSS-210, RSS-247
File: A04455 Short Term Conf IntPho r1

SN's: 39F004859 / 3401543685
FCC ID: IPH-04455
IC: 1792A-04455
Date: April 28, 2022
Page 7 of 9

Top Support PCB with shielding




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A04455
Test: 220124
Test to: CFR47 15C, RSS-210, RSS-247
File: A04455 Short Term Conf IntPho r1

SN's: 39F004859 / 3401543685
FCC ID: IPH-04455
IC: 1792A-04455
Date: April 28, 2022
Page 8 of 9

Top Support PCB shielding removed



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A04455
Test: 220124
Test to: CFR47 15C, RSS-210, RSS-247
File: A04455 Short Term Conf IntPho r1

SN's: 39F004859 / 3401543685
FCC ID: IPH-04455
IC: 1792A-04455
Date: April 28, 2022
Page 9 of 9