


Main Board top side shield installed



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: BB4113
Test: 200921
Test to: CFR47 15.C, RSS-210, RSS-247
File: BB4113 Short Term Conf IntPho

SN's: 3341634179 / 3341633959
FCC ID: IPH-A04113
IC: 1792A-A04113
Date: December 30, 2020
Page 1 of 6

Main Board top side shield removed




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: BB4113
Test: 200921
Test to: CFR47 15.C, RSS-210, RSS-247
File: BB4113 Short Term Conf IntPho

SN's: 3341634179 / 3341633959
FCC ID: IPH-A04113
IC: 1792A-A04113
Date: December 30, 2020
Page 2 of 6

Main Board Bottom side




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: BB4113
Test: 200921
Test to: CFR47 15.C, RSS-210, RSS-247
File: BB4113 Short Term Conf IntPho

SN's: 3341634179 / 3341633959
FCC ID: IPH-A04113
IC: 1792A-A04113
Date: December 30, 2020
Page 3 of 6

Sensor Board top side lens and shield antenna




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: BB4113
Test: 200921
Test to: CFR47 15.C, RSS-210, RSS-247
File: BB4113 Short Term Conf IntPho

SN's: 3341634179 / 3341633959
FCC ID: IPH-A04113
IC: 1792A-A04113
Date: December 30, 2020
Page 4 of 6

Sensor Board top side shield removed




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: BB4113
Test: 200921
Test to: CFR47 15.C, RSS-210, RSS-247
File: BB4113 Short Term Conf IntPho

SN's: 3341634179 / 3341633959
FCC ID: IPH-A04113
IC: 1792A-A04113
Date: December 30, 2020
Page 5 of 6

Sensor Board bottom side



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: BB4113
Test: 200921
Test to: CFR47 15.C, RSS-210, RSS-247
File: BB4113 Short Term Conf IntPho

SN's: 3341634179 / 3341633959
FCC ID: IPH-A04113
IC: 1792A-A04113
Date: December 30, 2020
Page 6 of 6