

**Applicant:** Garmin International

**Test Report S/N:** 45461849-R1.0, 45461850-R1.0

**FCC ID:** IPH-A04524

**ISED ID** 1792A-A04524

## **EXHIBIT 15 - PHOTOS - DUT INTERNAL**

Figure E15.1 - Internal, Back Cover Removed





Applicant: Garm

Test Report S/N:

Garmin International


45461849-R1.0, 45461850-R1.0

FCC ID:

IPH-A04524

**ISED ID** 1792A-A04524

Figure E15.2 - Internal, Front Removed





Applicant:

Garmin International

FCC ID:


IPH-A04524

**Test Report S/N:** 45461849-R1.0, 45461850-R1.0

ISED ID

1792A-A04524

Figure E15.3 – Internal, PCB Bottom Side





Applicant: Garmin

Garmin International

FCC ID:

IPH-A04524


Test Report S/N:

45461849-R1.0, 45461850-R1.0

ISED ID

1792A-A04524

Figure E15.4 - Internal, PCB Top Side





Applicant:

Garmin International

FCC ID:


IPH-A04524

**Test Report S/N:** 45461849-R1.0, 45461850-R1.0

ISED ID

1792A-A04524

Figure E15.5 - Internal, PCB Bottom Side, Shield Removed





Applicant: (

Test Report S/N:

Garmin International

45461849-R1.0, 45461850-R1.0

FCC ID:

1792A-A04524

IPH-A04524

Figure E15.6 - Internal, PCB Top Side, Shield Removed

