



External photographs of equipment under test



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA3256  
Test #: 170517  
Test to: CFR47 15C, RSS-Gen RSS-210  
File: AA3256 ExtPho

SN's: 3948708278 / 3948708275  
FCC ID: IPH-A3256  
IC: 1792A-A3256  
Date: August 18, 2017  
Page 1 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA3256  
Test #: 170517  
Test to: CFR47 15C, RSS-Gen RSS-210  
File: AA3256 ExtPho

SN's: 3948708278 / 3948708275  
FCC ID: IPH-A3256  
IC: 1792A-A3256  
Date: August 18, 2017  
Page 2 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA3256  
Test #: 170517  
Test to: CFR47 15C, RSS-Gen RSS-210  
File: AA3256 ExtPho

SN's: 3948708278 / 3948708275  
FCC ID: IPH-A3256  
IC: 1792A-A3256  
Date: August 18, 2017  
Page 3 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA3256  
Test #: 170517  
Test to: CFR47 15C, RSS-Gen RSS-210  
File: AA3256 ExtPho

SN's: 3948708278 / 3948708275  
FCC ID: IPH-A3256  
IC: 1792A-A3256  
Date: August 18, 2017  
Page 4 of 4