

Tune-up Procedure

Each unit is tested during unit production by measuring the output strength. The unit is then given pass/fail status based on the measured output strength. The pass/fail threshold is determined by engineering during product development. Compliant samples continue through production and non-compliant units are removed.

Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA3272
Test #: 171002 1212
Test to: CFR47 15C, RSS-247, RSS-210
File: AA3272 TunPro

SN's: 3958811086 / 1067
FCC ID: IPH-A3272
IC: 1792A-A3272
Date: January 12, 2018
Page 1 of 1