




Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA3654
Test: 191111
Test to: CFR47 15.C, RSS-210, RSS-247
File: AA3654 Short Term Conf TSup

SN's: 3310106727, 3310106805
FCC ID: IPH-A3654
IC: 1792A-A3654
Date: March 27, 2020
Page 1 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA3654
Test: 191111
Test to: CFR47 15.C, RSS-210, RSS-247
File: AA3654 Short Term Conf TSup


SN's: 3310106727, 3310106805
FCC ID: IPH-A3654
IC: 1792A-A3654
Date: March 27, 2020
Page 2 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA3654
Test: 191111
Test to: CFR47 15.C, RSS-210, RSS-247
File: AA3654 Short Term Conf TSup

SN's: 3310106727, 3310106805
FCC ID: IPH-A3654
IC: 1792A-A3654
Date: March 27, 2020
Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA3654
Test: 191111
Test to: CFR47 15.C, RSS-210, RSS-247
File: AA3654 Short Term Conf TSup

SN's: 3310106727, 3310106805
FCC ID: IPH-A3654
IC: 1792A-A3654
Date: March 27, 2020
Page 4 of 4