


Internal photographs of equipment under test

Top without Shielding




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA4094
Test: 210309a
Test to: CFR47 15C, RSS-210
File: AA4094 Short Term Conf IntPho

SN's: 3361278174, 381278190
FCC ID: IPH-A4094
IC: 1792A-A4094
Date: August 24, 2021
Page 1 of 5

Bottom side




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA4094
Test: 210309a
Test to: CFR47 15C, RSS-210
File: AA4094 Short Term Conf IntPho

SN's: 3361278174, 381278190
FCC ID: IPH-A4094
IC: 1792A-A4094
Date: August 24, 2021
Page 2 of 5

Rear Case, PCB removed with shielding



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA4094
Test: 210309a
Test to: CFR47 15C, RSS-210
File: AA4094 Short Term Conf IntPho

SN's: 3361278174, 381278190
FCC ID: IPH-A4094
IC: 1792A-A4094
Date: August 24, 2021
Page 3 of 5

Display rear side




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA4094
Test: 210309a
Test to: CFR47 15C, RSS-210
File: AA4094 Short Term Conf IntPho

SN's: 3361278174, 381278190
FCC ID: IPH-A4094
IC: 1792A-A4094
Date: August 24, 2021
Page 4 of 5

Antenna Locations



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA4094
Test: 210309a
Test to: CFR47 15C, RSS-210
File: AA4094 Short Term Conf IntPho

SN's: 3361278174, 381278190
FCC ID: IPH-A4094
IC: 1792A-A4094
Date: August 24, 2021
Page 5 of 5