
Main Board Top



Main Board Top with Shield



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Garmin International, Inc.

Model: CC3110 Test #: 190114

Test to: 47 CFR 15C, RSS-Gen RSS-247 File: CC3110 Short Term Conf IntPho


SN's: 4294967295 / B11 FCC ID: IPH-C03110 IC: 1792A-C03110 Date: February 12, 2019

Page 1 of 4

Main Board Bottom



Sensor Board Top



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Garmin International, Inc.


Model: CC3110 Test #: 190114

Test to: 47 CFR 15C, RSS-Gen RSS-247 File: CC3110 Short Term Conf IntPho


SN's: 4294967295 / B11 FCC ID: IPH-C03110 IC: 1792A-C03110 Date: February 12, 2019

Page 2 of 4

Sensor Board Top with Shield



Sensor Board Bottom



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Garmin International, Inc.


Model: CC3110 Test #: 190114

Test to: 47 CFR 15C, RSS-Gen RSS-247 File: CC3110 Short Term Conf IntPho

SN's: 4294967295 / B11 FCC ID: IPH-C03110 IC: 1792A-C03110 Date: February 12, 2019

Page 3 of 4

Antenna Location



Inside case



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Garmin International, Inc.

Model: CC3110 Test #: 190114

Test to: 47 CFR 15C, RSS-Gen RSS-247

File: CC3110 Short Term Conf IntPho

SN's: 4294967295 / B11 FCC ID: IPH-C03110 IC: 1792A-C03110 Date: February 12, 2019

Page 4 of 4