



Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: E3545
Test: 190806
Test to: CFR47 15.249
File: E3545 Short Term Conf TSup


SN's: 3998030586, 3998030578
FCC ID: IPH-E3545
IC: 1792A-E3545
Date: February 19, 2020
Page 1 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: E3545
Test: 190806
Test to: CFR47 15.249
File: E3545 Short Term Conf TSup

SN's: 3998030586, 3998030578
FCC ID: IPH-E3545
IC: 1792A-E3545
Date: February 19, 2020
Page 2 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: E3545
Test: 190806
Test to: CFR47 15.249
File: E3545 Short Term Conf TSup

SN's: 3998030586, 3998030578
FCC ID: IPH-E3545
IC: 1792A-E3545
Date: February 19, 2020
Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: E3545
Test: 190806
Test to: CFR47 15.249
File: E3545 Short Term Conf TSup

SN's: 3998030586, 3998030578
FCC ID: IPH-E3545
IC: 1792A-E3545
Date: February 19, 2020
Page 4 of 4