

Tune-up Procedure

No transmitter tune-up is required for the transceiver. Transceiver functional performance is measured both at the board level and at final test during production.

Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: O2AWGD00
Test #:120627 SN: 3846360698
Test to: FCC CFR 47 15.249, RSS 210
File: TunPro O2AWGD00

FCC ID: IPH-O2AWGD
IC: 1792A- O2AWGD
GPN: 011-02844-xx
Date: July 21, 2012
Page 1 of 1