

Internal photographs of equipment under test
Inside enclosure



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04167
Test: 210507
Test to: CFR47 15C, RSS-247
File: A04167 Short Term Conf IntPho

SN's: 3384066120/ 3384066079
FCC ID: IPH-04167
IC: 1792A-04167
Date: December 9, 2021
Page 1 of 9

Left PCB back side



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04167
Test: 210507
Test to: CFR47 15C, RSS-247
File: A04167 Short Term Conf IntPho

SN's: 3384066120/ 3384066079
FCC ID: IPH-04167
IC: 1792A-04167
Date: December 9, 2021
Page 2 of 9

Left PCB Front Side without Shield




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04167
Test: 210507
Test to: CFR47 15C, RSS-247
File: A04167 Short Term Conf IntPho

SN's: 3384066120/ 3384066079
FCC ID: IPH-04167
IC: 1792A-04167
Date: December 9, 2021
Page 3 of 9

Left PCB Front Side with Shield



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04167
Test: 210507
Test to: CFR47 15C, RSS-247
File: A04167 Short Term Conf IntPho

SN's: 3384066120/ 3384066079
FCC ID: IPH-04167
IC: 1792A-04167
Date: December 9, 2021
Page 4 of 9

Right PCB back Side without shield



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04167
Test: 210507
Test to: CFR47 15C, RSS-247
File: A04167 Short Term Conf IntPho

SN's: 3384066120/ 3384066079
FCC ID: IPH-04167
IC: 1792A-04167
Date: December 9, 2021
Page 5 of 9

Right PCB back Side with shield



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04167
Test: 210507
Test to: CFR47 15C, RSS-247
File: A04167 Short Term Conf IntPho

SN's: 3384066120/ 3384066079
FCC ID: IPH-04167
IC: 1792A-04167
Date: December 9, 2021
Page 6 of 9

Right PCB Front Side without shield



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04167
Test: 210507
Test to: CFR47 15C, RSS-247
File: A04167 Short Term Conf IntPho

SN's: 3384066120/ 3384066079
FCC ID: IPH-04167
IC: 1792A-04167
Date: December 9, 2021
Page 7 of 9

Right PCB Front Side with shield



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04167
Test: 210507
Test to: CFR47 15C, RSS-247
File: A04167 Short Term Conf IntPho

SN's: 3384066120/ 3384066079
FCC ID: IPH-04167
IC: 1792A-04167
Date: December 9, 2021
Page 8 of 9



5 GHz antenna

2.4 GHz Antenna

Rogers Labs, Inc.
 4405 West 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214
 Revision 1

Garmin International, Inc.
 HVIN: A04167
 Test: 210507
 Test to: CFR47 15C, RSS-247
 File: A04167 Short Term Conf IntPho

SN's: 3384066120/ 3384066079
 FCC ID: IPH-04167
 IC: 1792A-04167
 Date: December 9, 2021
 Page 9 of 9