





FCC ID: IQX97C1795


Reference modification letter: No.2



7N2805

FCC ID: IQX97C1795
Mechanical construction
Reference modification letter: No. 8

6




FCC ID: IQX97CL795
Mechanical construction
Reference modification letter: No.3

7N2805

FCC ID: IQX97CL795

Mechanical construction




4

7N2805


FCC ID: IQX97C1795

Reference modification letter: No.4



FCC ID: IQX97CL795


Mechanical construction



FCC ID: IQX97C1795

Mechanical construction


7N2805



7N2805

FCC ID: IQX97C1795

Front side of CRT board



7N2805


FCC ID: IQX97C1795

Rear side of CRT board

7N2805

FCC ID: IQX97C1795


Reference modification letter: No.5



FCC ID: IQX97C1795


Front side of main board

Reference modification letter: No.6



7N2805

FCC ID: IQX97C1795
Rear side of main board
Reference modification letter: No.7



7N2805


FCC ID: IQX97C1795
Mechanical construction



8

7N2805

FCC ID: IQX97C1795
Reference modification letter: No.8
(with USB PORT)



FCC ID: IQX97C1795

Reference modification letter: No.7
(with USB PORT)


7N2805



FCC ID: IQX97C1795

Reference modification letter: No.3
(with USB PORT)


7N2805



7N2805

FCC ID: IQX97C1795

Mechanica construction with USB port
Reference modification letter: No.2




FCC ID: IQX97C1795

Mechanical construction with USB port

Reference modification letter: No.2,4
5,6

7N2805



FCC ID: IQX97CL795

Front side of USB board