


Annex C: Internal photographs




171663_22.JPG: IUHF190V1B, internal view 1 (top housing removed)

Annex C: Internal photographs




171663_10.JPG: IUHF190V1B, internal view 2 (PCB 1 with antenna removed)

Annex C: Internal photographs




171663_11.JPG: IUHF190V1B, internal view 3 (PCB 2 removed)

Annex C: Internal photographs




171663_9.JPG: IUHF190V1B, internal view 4 (without rear cover)

Annex C: Internal photographs




171663_17.JPG: IUHF190V1B, internal view 5 (PCB 3 removed)

Annex C: Internal photographs




171663_6.JPG: IUHF190V1B, PCB 1, top view

Annex C: Internal photographs




171663_20.JPG: IUHF190V1B, PCB 1, bottom view (antenna removed)

Annex C: Internal photographs




171663_13.JPG: IUHF190V1B, PCB 2, top view

Annex C: Internal photographs




171663_16.JPG: IUHF190V1B, PCB 2, top view, shielding removed

Annex C: Internal photographs




171663_12.JPG: IUHF190V1B, PCB 2, bottom view

Annex C: Internal photographs




171663_18.JPG: IUHF190V1B, PCB 3, top view

Annex C: Internal photographs




171663_19.JPG: IUHF190V1B, PCB 3, bottom view

Annex C: Internal photographs



171663_7.JPG: IUHF190V1B, antenna, top view

Annex C: Internal photographs



171663_21.JPG: IUHF190V1B, antenna, bottom view