



## 4.6 Test Photographs



Front View



Rear View

Tel: 886-3-3226-888 Fax: 886-3-3226-881


Issued Date : Dec. 10, 2014

Report No.: TEFB1411095

Page No. : 19 of 91 FCC ID. : IRJ-MR10A7



## 5.8 Test Photographs (30MHz ~ 1GHz)



Front View



Rear View

Cerpass Technology Corp.

Tel: 886-3-3226-888 Fax: 886-3-3226-881

Issued Date : Dec. 10, 2014

Report No.: TEFB1411095


Page No. : 46 of 91 FCC ID. : IRJ-MR10A7



## 5.9 Test Photographs (1GHz ~ 25GHz)



Front View



Rear View

Cerpass Technology Corp.

Tel: 886-3-3226-888 Fax: 886-3-3226-881

Issued Date : Dec. 10, 2014

Report No.: TEFB1411095

Page No. : 47 of 91 FCC ID. : IRJ-MR10A7