




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster



EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




BDA 48710
D7W
Service Area Uplink
IM Test
TX=897Mhz,24dBm
TX=899Mhz,24dBm

EQUIPMENT: 48710 & 48722 Signal Booster




BDA 48722
D7W
Base DownLink
IM Test
TX=937Mhz,24dBm
TX=939Mhz,24dBm


EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster



EQUIPMENT: 48710 & 48722 Signal Booster



EQUIPMENT: 48710 & 48722 Signal Booster



EQUIPMENT: 48710 & 48722 Signal Booster

