


Appendix C. Set up Photograph

Conducted Emission Mode 1~2



FRONT VIEW

REAR VIEW



SPORTON International Inc. TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 : Page No.: C1 of C4Report Issued Date: May 04, 2006Report Version: Rev. 01







SIDE VIEW


SPORTON International Inc. TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 :




Report No. : FR641805



Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 :