

Spectralink Corporation

2560 55th Street, Boulder CO 80301, USA

Declaration of changes from Initial VC9253 to Variant VC9240

General: \_\_\_\_\_ is a variant product of \_\_\_\_\_.

● SOFTWARE MODIFICATIONS:

- > Protocol Stack changes: No
- > MMS/STK/USAT/USIM changes: No
- > DM/SUPL/VT/FUMO/SWP/HCI: No

Other changes detailed:

The only difference between these two SKUs is driver of scanner. One has driver code of scanner, the other one doesn't have it.

● HARDWARE MODIFICATIONS:

- > Baseband changes: NO
- > Band changes: NO
  
- > Antenna changes: YES
- > PCB Layout changes: NO
- > Main components changes: NO

	Antanna	AP	MODEM	Transceiver	Balun	Band pass filter	diplexer
Bluetooth	YES	NO	NO	NO	NO	NO	NO
wifi	YES	NO	NO	NO	NO	NO	NO

- > Bluetooth changes: Antenna different
- > WiFi changes: Antenna different
- > FM changes: NO
- > NFC changes: Antenna different
- > Other components changes: NO
- TP/LCD/ Camera changes: NO
- > Other changes detailed: Scanner different

● MECHANICAL MODIFICATIONS:

- Use new metal front/back cover or keypad: No change
- Mechanical shell changes:
  - Whole size of EUT: 133.2x65.98x19.38 (with scanner) 、 133.2x65.98x13.20 (Non scanner)
  - Distance of Ear reference point to bottom of handset: No change
  - Other trinkets to change the surface of handset: with scanner lens (with scanner)、 No scanner lens( Non scanner)
- Other changes detailed:
  - Different rear cover and antenna frame

APPROVED BY:

Project Manager:

Signature:

Date: