## 2019/3/14

Federal Communications Commission
Office of Engineering and Technology
Equipment Authorization Division
7345 Oakland Mills Road
Columbia, Maryland 21046

Subject: FCC Class II Permissive change for FCC ID: IYG95XX

To Whom It May Concern,

This is to request a Class II Permissive change for FCC ID: IYG95XX, granted on 2018.09.21.

## SOFTWARE MODIFICATIONS:

Protocol Stack changes: no

MMS/STK/USAT/USIM changes: no DM/SUPL/VT/FUMO/SWP/HCI: no

## HARDWARE MODIFICATIONS:

Baseband changes: NO Band changes: NO Antenna changes: NO Bluetooth changes: NO WiFi changes: NO

PCB Layout changes: NO

Main components changes: NO

NFC changes: NO

Other components changes: NO TP/LCD/ Camera changes: NO

Other changes detailed: Add a New Battery

According to the change detail, the test items below were performed.

1..BT/BLE

No test for radiated TCs, because no change on BT antenna.

2.WIFI

No test for 2.4G and radiated TCs, because no change on WIFI antenna.

Letter head

No test for 5G and TCs, because no change on WIFI antenna and power setting.

3.NFC

No test for NFC, because no change on NFC part.

1	c	۸	D
4	`	Д	к

Spot check for WIFI part, because adding a new battery.

Thank you.

Sincerely,

Contact Name: Robbins, Perry

Title:Principal Engineer

Company Name:Spectralink Corp

Company address:2560 55<sup>th</sup> Street Boulder, CO 80301 USA

Peny Rollin

Signature: