



2018-09-19

Federal Communication Commission
Equipment Authorization Division, Application Processing Branch
7435 Oakland Mills Road
Columbia, MD 21048

Certification and Engineering Bureau
Industry Canada
Spectrum Engineering Branch
3701 Carling Avenue, Building 94
Ottawa, Ontario K2H 8S2

PCII Request / Re-assessment

AK01, FCC ID: **IYZ-AK01** granted on 2014-06-11
and IC: **2701A-AK01** granted on 2015-03-26

TO WHOM IT MAY CONCERN

Pursuant to CFR § 2.1043 and RSP-100, Marquardt GmbH hereby requests a Permissive Change Class II / Re-assessment.

Reason:

Modifications:

- Changes to the tuning of the internal PCB antenna
- Introduction of pulldown-resistors on four microcontroller ports (no RF specific change)

The following new exhibits will be uploaded:

- Test report on radiated measurements
- RF Exposure Info
- Description of the changes incl. schematics
- External and internal photos

Sincerely,

MARQUARDT GMBH
78604 RIETHEIM-WEILHEIM

Thomas Schwarz, Vice President Engineering Services
Marquardt GmbH
Schloss-Str. 16, D-78604 Rietheim-Weilheim
+49 7424 99 1643

Marquardt GmbH • Schloss-Str. 16 • 78604 Rietheim-Weilheim • Germany
www.marquardt.de • marquardt@marquardt.de
Telefon +49 (0) 74 24 - 99 0 • Telefax +49 (0) 74 24 - 99 23 99

Geschäftsführung: Dr. Harald Marquardt (Vorsitzender) • Jochen Becker • Karl Müller • Dr. Gregor Schmeken
Vorsitzender des Aufsichtsrats: Rainer Hundsdörfer • Amtsgericht Stuttgart HRB 450295