

Lucy Tsai

From: sabrina.wang [sabrina.wang@tw.ccsemc.com] on behalf of spencer.ying [spencer.ying@tw.ccsemc.com]
Sent: Monday, January 21, 2008 1:57 AM
To: Lucy Tsai
Cc: julia.wei; sabrina.wang
Subject: FW: CAN TECHNOLOGY CO., LTD., FCC ID: IZICAN61977, Assessment NO.: AN08T7498, Notice#1
Attachments: RECEIVER001 User Manual 0121update.pdf

Dear Lucy:

Q#1: Internal photos indicates a monopole antenna and a printed antenna are used but test report only show the monopole antenna. Please address.

ANS:PCB Antenna is disabled.The Test report is modified, please refer to page 4 of the Test report .

Q#2: Please provide a block diagram to include all used oscillators per Part 2.1033.

ANS: The block diagram has modified, please refer to new block diagram.