



American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

December 26, 2001

RE: Xircom, Inc.

FCC ID: J3OM3AWEB56GA

I have a few comments on this Application.

- 1.) The FCC is still using Adobe 4.0 as their preferred document software. It is completely incompatible with the security settings you used in converting your Exhibits using Acrobat 5.0. I was not able to remove the encryption myself, so I must ask you to remove all encryption and upload all documents again to the American TCB website. Please use the word Revised in the MS-DOS file name.
- 2.) Please extract the test setup photos from the test report and add to the Test Setup photos Exhibit.
- 3.) It is not completely clear where the label will be placed in the card. Please provide photo or line drawing identifying where the label will be placed on the device.
- 4.) There is a statement in the Test Report which states that the Foxcom antenna is not part of the modular approval. Is this true? If so, why are you showing it in the RF Exposure report?
- 5.) There is a local oscillator which shows up ~400MHz below the carrier frequency. If the LO is present when the Tx is placed in Rx mode, or the transmitter final stage is turned off, it is considered an Unintentional emission, and therefore subject to the Class B limits. Was this emission investigated?
- 6.) A Confidentiality Request letter is required.
- 7.) Is a Part 68 Application for this device pending?

If you have any questions give me a call.

William H. Graff
President and Examining Engineer

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.