

Correspondence by Project

Project Number:

315947237

Correspondence Number	Memo
J69CB526-1	<p>1) Please provide a TCB contract. A TCB contract has been provided. 2) Please provide a diagram or photo showing the location of the FCC ID label. A sample diagram showing the label location has been provided. 3) The test report does not mention whether testing was performed below 30 MHz. Please clarify whether testing was performed below 30 MHz and the results. Testing was performed below 30 MHz and no emissions were found. 4) Please provide documentation to show RF exposure compliance. A document explaining SAR exclusion has been provided. 5) Please provide external photos. Please see the external photos that have been provided. 6) Please provide internal photos. Please see the internal photos that have been provided. 7) The user manual states that a supervisory transmission is sent, however the test report states that the EUT has no supervision transmissions. Please provide clarification regarding the operation of the device and provide updated documentation as required. Supervisory transmissions are not used, please see the amended user manual.</p>