

11. SETUP PHOTOS


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



Page 101 of 107

RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







Page 102 of 107

UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.


RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)







UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION






Page 104 of 107



Page 105 of 107

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



Page 106 of 107



END OF REPORT

Page 107 of 107