

A面

DPI indicator

Battery Percentage	DPI indicator Effect
<5%	Flashing red light continuously
<10%	Flashing red light for 5 seconds
<20%	Flashing red light for 5 seconds
20%-99%	No effect
100%	Static Green light (In charging mode)

- You can view more detailed battery status through the GIGABYTE Control Center.

DPI	DPI indicator light
800(Default)	White
1600	Yellow
3200	Cyan
6400	Magenta

- You can change your mouse's DPI to match your playstyle with a press of the DPI cycle button or fine-tune your own sensitivity setting using the GIGABYTE Control Center.

12QM-000AM6-0*R



Wireless Gaming Mouse AORUS M6 | Quick Guide


GETTING STARTED

- Please fully charge your mouse before using it for the first time.
- A depleted battery will be fully charged in approximately 3 hours.
- If your mouse has not been used for an extended period, you may need to recharge it before use.
- The mouse requires a USB connection that can supply sufficient power to charge the battery, and this connection also acts as the wired mode for your mouse.
- When charging begins after the charging cable is connected, the DPI indicator will show a static green light for 5 seconds.


* 廠商料號尾碼需更新

B面

How to activate the mouse?



How to charge the battery?



材質: 100P 道林紙 / 雙面單色印刷

折合方式: 對折

展開尺寸: 148 x 105mm

折合尺寸: 74 x 105mm

[折合方式示意]

