



HERMON LABORATORIES

November 4, 2004

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. Timothy Johnson, Examining Engineer

RE: your e-mail dated November 3, 2004; Rokonet Electronics Ltd.
FCC ID:JE4RK200DT, ATCB001804

Dear Mr. Johnson,
Please find below the answer to your question:

- 1) Rokonet Electronics revised the operational description and states that operating frequency is 10525 ± 10 MHz. The Operational_description_16071_rev1 file was uploaded on November 4, 2004 via Operational Description folder.

Plot 7.2.1 – it was the relative measurement 50 dB attenuation down from the carrier, at band edges, performed with the same RBW at both carrier and band edges frequencies.

Many thanks for your attention to these matters.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories