Mike Kuo

 From:
 SS [ssliou@etc.org.tw]

 Sent:
 June15日2004年Tuesday 11:03 PM

 To:
 Mike Kuo

 Subject:
 Re: MASCOT ELECTRIC CO., LTD., FCC ID: JEBUT-9, Assessment NO.: AN04T3961



Exhibit-C-Test_Rep Exhibit-K-Tune_up_Exhibit-E-User's_Ma ort_revised_... procedure_re... nual_revise...

Dear Mike,

Replying your questions:

Please refer to attached page 2 of revised test report.
 Please refer to attached revised tune-up procedure. The misleading pages were removed.
 Please refer to attached page 8 of revised user manual. The frequency range was corrected.

Best regards,

S. S. Liou Engineer / EMC Dept. II Electronics Testing Center, Taiwan

----- Original Message -----From: "etcemi" <etcemi@seed.net.tw> To: "R00/???" <ssliou@etc.org.tw> Cc: <kevin@etc.org.tw> Sent: Tuesday, June 08, 2004 9:53 AM Subject: Fw: MASCOT ELECTRIC CO., LTD., FCC ID: JEBUT-9, Assessment NO.: AN04T3961 > > ----- Original Message -----> From: "Mike Kuo" <MKUO@CCSEMC.com> > To: "ETC/Iris (E-mail)" <etcemi@seed.net.tw> > Sent: Tuesday, June 08, 2004 6:18 AM > Subject: FW: MASCOT ELECTRIC CO., LTD., FCC ID: JEBUT-9, Assessment NO.: > AN04T3961 > > >> >> >> -----Original Message----->> From: Compliance Certification Services [mailto:MKuo@ccsemc.com] > > Sent: Monday, June 07, 2004 2:58 PM >> To: mkuo@ccsemc.com > > Subject: MASCOT ELECTRIC CO., LTD., FCC ID: JEBUT-9, Assessment NO.: > > AN04T3961 >> > > >> Question #1: Page 2 of test report listed the frequency range which does > not> > agree with TCB application form. Please make necessary correction. >> > > Question #2: In the tune up procedures, there are total of four pages > which >> listed the frequency range. Page 3 and 4 of tune up procedure listed the >> frequency range are beyond the 770MHz. Please explain. >>

> > Question #3: The transmitter technical specification listed the frequency

> > range is from 630-928MHz which do not agree with frequency range from

>> 630-660 MHz and 740 - 770 MHz. Please explain.

>>

> > Best Regards

> > > > Mike Kuo

>>

> > The items indicated above must be submitted before processing can continue

> > on the above referenced application. Failure to provide the requested

>> information within 60 days of the original e-mail date may result in >> application dismissal and forfeiture of the filing fee. Also, please

note

>> that partial responses increase processing time and should not be > submitted.

> > Any questions about the content of this correspondence should be directed

> to
> the e-mail address listed below the name of the sender.

>