

May. 22th, 2018

Letter of Attestation

Model: TS-890S Scanning receiver (FCC ID: K44512000)

This letter attests to the fact that KENWOOD scanning receiver model TS-890S meets the requirements of the FCC Rules, 15.121(a). Compliance is achieved through the following method(s):

- (1). The Microprocessor employed has internal flash memory, however the programming information cannot be read out from the Microprocessor, therefore it has same means of protection as a masked Microprocessor .
- (2). The Microprocessor is not to accept programming, selection, scanning or direct entry of Cellular band frequencies.
- (3). Filtering precludes reception of mixer images or harmonics of Cellular band frequencies.
- (4). It is subminiature SMD assembly and inaccessible multiplayer PCB construction, any attempts to modify the equipment to receive transmissions from the Cellular Radiotelephone Service likely will render the receiver inoperable.



Tamaki Shimamura
Communication Systems Division
JVC KENWOOD Corporation