



VX-231-AG6B-5 and BC95 Interior Comparison


VX-231-AG6B-5 Side-A of Main-Unit




BC95 Side-A of Main-Unit



VX-231-AG6B-5 Side-B of Main-Unit



BC95 Side-B of Main-Unit



Change of only a MIC/SP Jack