

YAESU U.S.A.
U.S. HEADQUARTERS
17210 EDWARDS ROAD
CERRITOS, CA 90709
TEL: 562.404.2700
FAX: 562.404.1210

February 14, 2000

Federal Communications Commission
Authorization & Evaluations Division
7435 Oakland Mills Road
Columbia, MD 21046


Reference: FCC ID: K66VX-110

Gentlemen:

With regard to your new FCC Rule 15.121(f) that pertains to scanning receivers, we will apply a label on our radios that will have the statement shown below. We will also print this statement in all Owners' Manuals.

**WARNING: MODIFICATION OF THIS DEVICE TO RECEIVE CELLULAR
RADIOTELEPHONE SERVICE IS PROHIBITED UNDER FCC RULES
AND FEDERAL LAW.**

Best regards,


Mikio Maruya
Executive Vice President

MM/fm