



Intertek Testing Services

ETL SEMKO

Report No.: 0008502
Mode: Talk

Tested By: Hong, Report No.: 0008502

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0008502
Mode: Talk

Tested By: Hong, Report No.: 0008502

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
-----------	----------	----------

MHz	dBuV	dBuV
-----	------	------

0.53000	29.7	48.0
---------	------	------

0.59000	27.3	48.0
---------	------	------

0.98000	19.5	48.0
---------	------	------

1.25500	20.4	48.0
---------	------	------

1.29500	20.2	48.0
---------	------	------

* limit exceeded