




**BUREAU  
VERITAS**


Reference No.: 2101WDG0287-1

## SET-UP FOR RF EXPOSURE TEST


**Electric Field (Standby)**




**Electric Field (Charging mode with receiver load)**




### Magnetic Field (Standby)




### Magnetic Field (Charging mode with receiver load)




Distance 2 cm




Distance 4 cm




Distance 6 cm



Distance 8 cm




Distance 10 cm




Left




Right



Bottom



Top



Z-axis

