

## FCC ID: K7SF8T060xDNGL

Issued on May 17, 2004

## 5.8.5. Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



**FRONT VIEW** 



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID. : K7SF8T060xDNGL

Report No.: F3D0512

Page No. : 34of 39 Issued Date : May 17, 2004



5.7.4.

## FCC ID: K7SF8T060xDNGL Issued on May 17, 2004

• The photographs show the configuration that generates the maximum emission.

Photographs of Conducted Emission Test Configuration



**FRONT VIEW** 



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID. : K7SF8T060xDNGL

Report No.: F3D0512

Page No. : 26of 39 Issued Date : May 17, 2004