




REV NO	ECN	PLACE	ORIGINAL SIZE	CHANGE SIZE	CAUSE	DRAFTER	CHECKED	DATE
△	N/A	N/A	原設計圖	N/A	N/A	施冠宇	林家毅	HC13
△					增加RR-2A跟AT-R2-1型號	施冠宇	林家毅	L721



Model No:  
 1001-B  1420-B  
 RR-1A-B  
 AT-R1-1B

Date Code:  
'22 

1	2	3	4	5	6
7	8	9	10	11	12

  
'23 

1	2	3	4	5	6
7	8	9	10	11	12

FCC ID:K9L1001R2TX  
IC:2439A-1001R2TX

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE AND(2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIREED OPERATION.  
SKYTECH II,INC  
MADE IN CHINA

Model No:  
 1001-B  1420-B  
 RR-1A-B  
 AT-R1-1B

Date Code:  
'22 

1	2	3	4	5	6
7	8	9	10	11	12

  
'23 

1	2	3	4	5	6
7	8	9	10	11	12

FCC ID:K9L1001R2TX  
IC:2439A-1001R2TX

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE AND(2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIREED OPERATION.  
SKYTECH II,INC  
MADE IN CHINA

Model No:  
 1001-B  1420-B  
 RR-1A-B  
 AT-R1-1B

Date Code:  
'22 

1	2	3	4	5	6
7	8	9	10	11	12

  
'23 

1	2	3	4	5	6
7	8	9	10	11	12

FCC ID:K9L1001R2TX  
IC:2439A-1001R2TX

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE AND(2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIREED OPERATION.  
SKYTECH II,INC  
MADE IN CHINA

1:1

工程編輯版

廠商印刷版

註解：  
材質：環保PVC  
厚度：0.25mm  
顏色：綠底黑字  
需背膠  
尺寸誤差為正負0.2mm

2:1

RoHS	確認	審核	繪圖	設計

FILE ADDRESS

協記精密工業股份有限公司 FEGO PRECISION INDUSTRIAL CO.,LTD.		DRAFTER	施冠宇	DATE	L721
MATERIAL:	THIRD ANGLE PROJ.	DESIGNER	施冠宇	DATE	L721
		CHECKED	林家毅	DATE	L721
UNIT:	mm	DWG NO	CD13	TYPE	1420-B_FCC
SCALE:	1:1	PART NO	3NC	NAME	FCC_IC標貼

# **VR-1A-B**

## **DATE CODE: YYMM**

**IC: 2439A-1001R2TX**  
**FCC ID: K9L1001R2TX**

**THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION. NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.**

**SKYTECH II, INC MADE IN TAIWAN**

# **SR1001-B**

## **DATE CODE: YYMM**

**IC: 2439A-1001R2TX**  
**FCC ID: K9L1001R2TX**

**THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION. NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.**

**SKYTECH II, INC MADE IN TAIWAN**



# **SP1001TX-B**

## **DATE CODE: YYMM**

**IC: 2439A-1001R2TX**  
**FCC ID: K9L1001R2TX**

**THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION. NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.**

**SKYTECH II, INC MADE IN TAIWAN**

**SP1001H-LTX-B**

**DATE CODE: YYMM**

**IC: 2439A-1001R2TX**

**FCC ID: K9L1001R2TX**

**THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION. NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.**

**SKYTECH II, INC MADE IN TAIWAN**

**RCAF-1035-B**  
**DATE CODE: YYMM**

**IC: 2439A-1001R2TX**  
**FCC ID: K9L1001R2TX**

**THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION. NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.**

**SKYTECH II, INC MADE IN TAIWAN**



**RCAF-1031-4B**

**DATE CODE: YYMM**

**IC: 2439A-1001R2TX**

**FCC ID: K9L1001R2TX**

**THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION. NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.**

**SKYTECH II, INC MADE IN TAIWAN**



# **RCAF-1020-B**

## **DATE CODE: YYMM**

**IC: 2439A-1001R2TX**  
**FCC ID: K9L1001R2TX**

**THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION. NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.**

**SKYTECH II, INC MADE IN TAIWAN**

**RCAF-3TX-B**  
**DATE CODE: YYMM**

**IC: 2439A-1001R2TX**  
**FCC ID: K9L1001R2TX**

**THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION. NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.**

**SKYTECH II, INC MADE IN TAIWAN**

**CON1001-B**  
**DATE CODE: YYMM**

**IC: 2439A-1001R2TX**  
**FCC ID: K9L1001R2TX**

**THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION. NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.**

**SKYTECH II, INC MADE IN TAIWAN**



# **AT-V1-1B**

## **DATE CODE: YYMM**

**IC: 2439A-1001R2TX**  
**FCC ID: K9L1001R2TX**

**THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION. NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.**

**SKYTECH II, INC MADE IN TAIWAN**