



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

December 16, 2004

RE: D-Link Corporation

FCC ID: KA2G700APA1

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

1.) The label for this product is incorrect. The wrong FCC ID is shown. In addition, since no modular approval is involved, the reference to a specific ID contained inside this device is not appropriate. Kindly supply a label that correctly references the entire access point.

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.